Deerfield Watershed Bi-Weekly Report

Presented by the Deerfield River Watershed Association

Deerfield River Edition - Summer 2020

Water Quality Monitoring Sites		E. coli Results (organisms per 100 mL water)									
Town	Monitoring Location	7/8	7/22	8/5	8/19	9/2*	9/16				
North Branch Deerfield River											
Wilmington, VT	Above Wilmington Center	276	613	NT	261	167	61				
	Wilmington Center, Below Beaver Brk	345	579	NT	276	816	326				
Deerfield River											
Charlemont, MA	Shunpike Rest Area	93	50	NT	15	105	13				
	Near Academy at Charlemont	40	79	NT	38	39	20				
Shelburne, MA	Sunburn Beach, upstream of North R.	66	16	NT	31	30	22				
Deerfield, MA	Stillwater Bridge	20	23	NT	48	96	26				
	Behind Deerfield Academy	38	45	NT	30	44	47				
Greenfield	5 & 10 Bridge	56	76	NT	55	105	58				

Bold-Italics = Exceeds VT & EPA "suitability for swimming" standard of 235 E. coli /100 mL H2O

NT = Not tested NA= Not available >2420 = E. coli count exceeded the upper limit of the test method used

These results represent a snapshot of the river conditions at the moment the sample was taken. Not all monitoring locations are suitable or swimming or on public property. Please be aware that conditions can and do change over time, especially in relation to weather.

Bacteria levels are typically elevated during and shortly after wet weather events. It is recommended to wait 24-48 hours after significant rainfall to resume swimming in lakes and streams. The US EPA recommends *E. coli* as an indicator of health risk from water contact in recreational waters. Swim at your own discretion.

DRWA's water quality monitoring program is supported by our volunteers, members, and donors, including Green River Watershed Alliance, Massachusetts Department of Environmental Protection & Connecticut River Conservancy.









^{* =} Heavy rains occurred within 24 hours preceding this river sampling

Deerfield Watershed Bi-Weekly Report

Presented by the Deerfield River Watershed Association

Deerfield Tributary Edition - Summer 2020

Water Quality Monitoring Sites		E. coli Results (organisms per 100 mL water)									
Town	Monitoring Location	7/8	7/22	8/5	8/19	9/2*	9/16				
Green River Mainstem											
Guilford, VT	Downstream of Timber Crib Dam	61	517	NT	55	613	24				
Colrain, MA	Bare Ass Beach	70	40	NT	146	54	29				
Greenfield, MA	Between MA-2A & RR Bridge	236	687	NT	326	291	138				
Beaver Brook											
Wilmington, VT	VT Route 9, near Wahoo's	411	548	NT	1553	687	17				
North River											
Whitingham, VT	Route 112 Bridge, north of 8A (East Branch)	261	687	NT	17	115	125				
Colrain, MA	Foundry Village Rd Ballfields (East Branch)	91	52	NT	64	121	34				
Shelburne, MA	Sunburn Beach, upstream of Deerfield R.	43	81	NT	65	66	22				
Clesson Brook											
Buckland, MA	Behind Buckland Rec Area	126	179	NT	56	101	47				
South River											
Conway, MA	Reeds Bridge Rd	184	214	NT	54	26	27				
D 1111 F											

Bold-Italics = Exceeds VT & EPA "suitability for swimming" standard of 235 E. coli /100 mL H2O

NT = Not tested NA= Not available >2420 = E. coli count exceeded the upper limit of the test method used

These results represent a snapshot of the river conditions at the moment the sample was taken. Not all monitoring locations are suitable or swimming or on public property. Please be aware that conditions can and do change over time, especially in relation to weather.

Bacteria levels are typically elevated during and shortly after wet weather events. It is recommended to wait 24-48 hours after significant rainfall to resume swimming in lakes and streams. The US EPA recommends *E. coli* as an indicator of health risk from water contact in recreational waters. Swim at your own discretion.

DRWA's water quality monitoring program is supported by our volunteers, members, and donors, including Green River Watershed Alliance, Massachusetts Department of Environmental Protection & Connecticut River Conservancy.









^{* =} Heavy rains occurred within 24 hours preceding this river sampling